

### PRO-Z SERIES (PRO-Z 100 Series)

#### **ATTENTION: MANDATORY ACTION REQUIRED**

**Models Affected:** PRO-Z 100 EFI 148-L (53TWEHRF050)  
PRO-Z 100 EFI 148-S (53RWEFJF050, 53TWEFJF050).  
PRO Z 100 EFI 154-L (53RWEHRA050, 53TWEHRA050).  
PRO Z 100 EFI 154-S (53RWEFJA050, 53TWEFJA050).  
PRO Z 100 EFI 160-L (53TWEHRU050).  
PRO Z 100 EFI 160-S (53RWEFJU050, 53TWEFJU050).

**Serial Number Range Affected:** January 01, 2017 through September 14, 2023  
(1A017H3xxxx through 1I14PHxxxxx)

**Date:** May 26, 2017 Revised September 15, 2023 (Please Destroy All Other Copies).

**Subject:** Possible Kinked Oil Lines On The Remote Oil Filter

**MANDATORY REPAIR**


**NOTE:** These materials are prepared for use by trained technicians who are experienced in the service and repair of equipment of the kind described in this publication, and are not intended for use by untrained or inexperienced individuals. Such individuals should seek the assistance of an authorized service technician or dealer.

**NOTE:** Always wear eye protection while servicing equipment. Wear hearing protection when appropriate. Always work in a well ventilated area and follow all safety precautions when dealing with combustible materials.

**NOTE:** Left (LH) and Right (RH) sides are determined from the operator's position and facing in the forward direction.

#### **PURPOSE:**

We have received reports of the oil lines possibly being kinked. This can cause the engine to be compromised of sufficient oil lubrication. Figure 1 shows one of the remote oil lines kinked.



**FIGURE 1**

#### **MANDATORY ACTION REQUIRED:**

1. Please inspect all PRO-Z 100 Models listed above in your dealer inventory. Follow the procedures listed on page 2 of this Advisory for inspecting the remote oil lines and removing the kink if needed.

