



Service Advisory

ZERO TURN SERIES

CC-545A

Models Affected: **RZT 42** (17BA5A4G709, 17BA5A4G710, 17AA5B4G709, 17AA5B4G710, 17AA5B4G756, 17AE2ACG010, 17AE2ACG709, 17AE2ACG710, 17AE2ACG756).
RZT 50 (17AA5B7P710, 17AA5B7P756, 17AA5D7P709, 17AA5D7P710, 17AA5D7P756, 17BA5A7P709, 17BA5A7P710, 17BA5A7P712, 17AI2ACP010, 17AI2ACP710, 17AI2ACP009, 17AI2ACP709, 17AI2ACP056, 17AI2ACP256, 17AI2ACP756, 17RI2ACP056, 17RI2ACP256).

Serial Number Range Affected: 1B175G through 2009. (February 17, 2005 through 2009).

Date: September 05, 2006 **Revised On August 14, 2009 (Destroy All Previous Copies).**

Subject: **Failure Of Welds Of The P.T.O. Clutch Torque Bracket To The Frame.**

IMPORTANT ATTENTION PARTS MANAGER ATTENTION SERVICE MANAGER

SOLUTION:

If a failure of the welds on the P.T.O. Clutch Torque Bracket occurs the replacement of the frame is *No Longer* needed. A P.T.O. Clutch Torque Bracket **603-04290B-0637** is now available as a bolt on service replacement part.

NOTE: 603-04290B-0637 replaces 603-04290A-0637.



603-04290B-0637 Clutch Torque Bracket.

Please Make a note of the part number **603-04290B-0637** P.T.O. Clutch Torque Bracket in your parts IPL or business system.

Warranty: Normal warranty terms apply. Indicate Service Advisory **CC-545A** and (**See Note Below**) for the original failed part to list on the claim. Repair time allowance is 1.0 Hrs.

NOTE: Part Numbers for the frame that can be listed on the claim for the original failed part are, 603-04303, 603-04303B, 603-04303C, 603-04303E or 603-04691.

SERVICE MANAGER	PARTS MANAGER	SALES MANAGER	SERVICE TECH.	SERVICE TECH.

Circulate and Initial