Service Advisory

CC-412

SERIES 3000 TRACTOR

Models: 3165, 3184, 3185, 3186, 3205, 3206, 3208, 3225, 3235

Date: March 14, 2001

Subject: HYDROSTATIC PUMP AND SHAFT

Hydrostatic pump part number 618-3142 and pump shaft part number HG-50984 have been discontinued by our supplier. Stocks of these parts are to be used until depleted. When depleted, order the appropriate kit as specified in the charts.

The charts list a tapered and splined design. The pictures below show the difference between the two designs.

618-3142 Hydrostatic Pump (Pump Model # BDU-21L 500) **Tapered**	**759-3967**	**Hydrostatic Pump Kit** (Pump Model # BDU-21L 501) **Splined**	**consists of:**
When depleted order 759-3967	PART NUMBER	DESCRIPTION	QTY
	618-3214	Hydrostatic Pump - Splined	1
	748-3093	Hub - Splined	1
	736-0253	Bell Washer	1
	712-3059	Nut ½-20	1
	731-3297	Fan	1

HG-50984 Pump Shaft Tapered	**759-3968**	**Pump Shaft Kit Splined**	**consists of:**
When depleted order 759-3968	PART NUMBER	DESCRIPTION	QTY
	HG-51206	Pump Shaft - Splined	1
	748-3093	Hub - Splined	1
	736-0253	Bell Washer	1
	712-3059	Nut ½-20	1
	731-3297	Fan	1

TAPERED DESIGN

SPLINED DESIGN

Please make a note of this information in your Series 3000 Parts Catalog (772-9089) and Dealer Business System.

Service Manager	Parts Manager	Sales Manager	Service Tech.	Service Tech.

Circulate and Initial