

PRO-Z SERIES (PRO-Z 500-S , 700-S, 900-S)

Date: August 21, 2024 **Revised April 30, 2025 (Please Destroy All Previous Copies)**

- PRO-Z 500**
Models Affected: **EFI 554-S** (53RWHJUN050).
KW 554-S (53RIHJUN050, 53RIHTUN050, 53TIHJUN050).
KW 560-S (53LIHJUV050, 53RIHJUV050, 53RIHTUV050, 53TIHJUV050).
- PRO-Z 700**
Models Affected: **EFI 754-S** (53REHKUN050).
KW 754-S (53FIHTUN050, 53TIHTUNA50).
EFI 760-S (53REHKUV050).
KW 760-S (53FIHTUV050, 53RIHKUV050, 53TIHKUV050, 53UIHTUV050, 53TIHTUVA50).
KW 772-S (53RIHKUY050).
- PRO-Z 900**
Models Affected: **EFI 960-S** (53REHMUV050).
KW 960-S (53RIHMUV050, 53RIHUUV050, 53RLHUUV050, 53TIHMUV050, 53FLHUUVA50).
KW 960-S SurePath (53RIHMAV050).
KW 972-S (53FIHMUY050, 53RIHMUY050, 53RIHUUY050, 53RLHUUY050).
KW EFI 972-S (53FLHUUYA50).
KW 972-SD Dually (53RLHVUY050, 53TIHMUY050, 53FLHVUYA50).
KW 972-SDL Dually (53FLLMUY050, 53RLHMUY050, 53RLLMUY050, 53RLLVUY050, 53TILMUY050, 53FLLVUYA50).
KW 972-S SurePath (53RIHMAY050).

Serial Number
Range Affected: Model Year 2016 and Forward.

Subject: PRO-Z Alignment Fixture Tool Kit 759-05122 INFORMATIONAL ONLY

PURPOSE:

This Advisory is to notify Dealers of the Alignment Fixture Tool Kit **759-05122** used for setting neutral and timing the synchro-steer mechanism on 2016 and forward, Cub Cadet **PRO-Z 500-S, 700-S** and **900-S** Series steering wheel model riders. Instructions for units manufactured with Hydro Gear Transmission have been added to the Service Kit instructions (**769-11701B**).

The Service Kit **759-05122** will consist of a Right Hand Fixture Tool and a Left Hand Fixture Tool along with hardware and instructions for "Setting Neutral On The Cub Cadet PRO-Z Series" and "Timing The Cub Cadet PRO-Z Series Synchro-Steer Mechanism".

759-05122 Service Kit Contents

ITEM NO.	PART NUMBER	QTY	DESCRIPTION
1	Not Available	2	SS ALIGNMENT PLT
2	Not Available	6	SS ALIGNMENT PIN
3	Not Available	6	1/4-20 NYLON FLGLK NUT
4	Not Available	2	LANYARD CBL
5	Not Available	2	1/4 X 4.50" HGE PIN

Instruction sheet included with kit.




FIGURE 1

NOTE: Additional Hardware Is Needed, not supplied with the Service Kit. Quantity (2) 1/4-20 x 1-1/2" Hex Head Cap Screws. (Not Shown). Source locally.

This Advisory is being released for informational purposes only.