



Service Bulletin

CC-326

LAWN TRACTORS AND SERIES 2000

Models: 2185
 Date: May 20, 1996
 Subject: Kohler Fuel Filter

PROBLEM: Current production tractors use a different fuel filter than the one shown in the Parts Catalog.

SOLUTION: Kohler has changed the fuel filter from a 51 micron filter P/N KH-25-050-03 to a 15 micron filter P/N KH-24-050-02. When replacing the fuel filter on the above model tractor, replace with the 15 micron filter.

Please make a note of this change in the above model Parts Catalog. Shelby Parts Depot will currently continue to supply the 51 micron filter for other applications.

This is being released as a bulletin for information purposes only.

Service Manager	Parts Manager	Service Tech.	Service Tech.	Service Tech.

Circulate And Initial