



Service Advisory

HOME MAINTENANCE

CC-555A

Models Affected: RZT 22 (17AA5A7P710, 712). RZT 50 (17AA5D7P709, 710, 756), (17BA5A7P709, 710, 712), (17AA5B7P710, 756)


Serial Number Range Affected: 2004 through 2006

Date: December 13, 2006 Revised October 31, 2011 (Destroy All Previous Copies).

Subject: Service Replacement Hydro Transmissions 759-04144 & 759-04145

IMPORTANT ATTENTION PARTS MANAGER ATTENTION SERVICE MANAGER


These Service Kits will replace the LH & RH hydro transmission part numbers 618-04164, 618-04164A, 618-04327 & 618-04163, 618-04163A, 618-04326 when stock is depleted. The replacement transmission has a Double-D axle which requires a Double-D wheel hub assembly. The LH Transmission Service Kit 759-04144 & the RH Transmission Service Kit 759-04145 will include the items shown below.



759-04144 Service Kit Contents

ITEM NO.	PART NUMBER	QTY	DESCRIPTION
1	618-04317	1	HUB ASM: WHL:DOUBLE-D LONG
2	618-04431B	1	TRANS ASM: HYDRO:EZT:LH
3	710-3119	1	SCREW:3/8"-16 x .750:GR5:LOCK
4	736-0227	1	WASHER:FLAT: .390 x 1.50 x .134
5	732-04448	1	SPRING:EXTENSION (See page 2)

Instruction Sheet included with kit.



759-04145 Service Kit Contents

ITEM NO.	PART NUMBER	QTY	DESCRIPTION
1	618-04317	1	HUB ASM: WHL:DOUBLE-D LONG
2	618-04432B	1	TRANS ASM: HYDRO:EZT:RH
3	710-3119	1	SCREW:3/8"-16 x .750:GR5:LOCK
4	736-0227	1	WASHER:FLAT: .390 x 1.50 x .134
5	732-04448	1	SPRING:EXTENSION (See page 2)

Instruction Sheet included with kit.

Please make a note of this information in your business system and parts manuals.

This Advisory is being released for informational purposes only.

SERVICE MANAGER	PARTS MANAGER	SALES MANAGER	SERVICE TECH.	SERVICE TECH.

Circulate and Initial