

SERIES 2000 TRACTOR


Models: 2130, 2135, 2140, 2145, 2150, 2155, 2160, 2165, 2185
 Serial Number 239,001 and after.
 Serial Number/Mfg Date prior to 1H157G.

Date: May 1, 2000

Subject: MUFFLER AND EXHAUST PIPE

We have been notified of a service replacement parts issue for the above serial number tractors concerning mufflers and exhaust pipes. When depleted, they will be discontinued for service. As current stock becomes depleted, order the appropriate **MUFFLER SERVICE KIT**. Part numbers and illustrations identify the affected parts.

MODELS 2130, 2135, 2140, 2145, 2150, 2155
 DISCONTINUED PARTS*



<u>PART NUMBER</u>	<u>DESCRIPTION</u>
703-2846	Exhaust Pipe Shield use with 751-3120 (Kohler)
751-3120	Exhaust Pipe w/attached baffle (Kohler)
703-2845	Exhaust Pipe Shield
703-2847	Exhaust Shield Rear
751-3137	Exhaust Pipe (Kohler)
751-3131	Exhaust Pipe (Onan/Linamar)
951-3000A	Muffler Assembly
759-3794	Muffler Assembly w/shields (Kohler)
759-3795	Muffler Assembly w/shields (Onan/Linamar)

MODELS 2130, 2135, 2150, 2155
759-3943 MUFFLER SERVICE KIT

consists of


<u>PART NUMBER</u>	<u>DESCRIPTION</u>	
KH-M-0841080	Flange Nut M8-1.25	Qty 2
KH-12-041-03	Exhaust Gasket	Qty 1
703-3099	Exhaust Pipe Shield	Qty 1
910-1268	Hex Screw #10-16 x .375	Qty 3
912-3004A	Flange Nut 5/16-18	Qty 3
751-0653	Exhaust Pipe (Kohler)	Qty 1
951-3001	Muffler Assembly	Qty 1

MODELS 2140, 2145


759-3941 MUFFLER SERVICE KIT

consists of

<u>PART NUMBER</u>	<u>DESCRIPTION</u>	
ME-155-2378	Exhaust Casket	Qty 1
703-3099	Exhaust Pipe Shield	Qty 1
910-1268	Hex Screw #10-16x.375	Qty 3
710-3175	Cap Screw M8-1.25 x 14 mm	Qty 2
912-3004A	Flange Nut 5/16-18	Qty 3
751-0806	Exhaust Pipe (Onan/Linamar)	Qty 1
951-3001	Muffler Assembly	Qty 1



**MODEL 2160, 2165, 2185
DISCONTINUED PARTS***



<u>PART NUMBER</u>	<u>DESCRIPTION</u>
703-2845	Exhaust Pipe Shield
703-2847	Exhaust Shield Rear
751-3122	Exhaust Pipe (Vanguard Twin)
751-3139	Exhaust Pipe (Vanguard Twin)
751-3121	Exhaust Pipe (Kohler Twin)
751-3138	Exhaust Pipe (Kohler Twin)
951-3000A	Muffler Assembly
759-3795	Muffler Assembly w/shields (Vanguard & Kohler Twin)

**MODELS 2160, 2165
759-3942 MUFFLER SERVICE KIT**


consists of

<u>PART NUMBER</u>	<u>DESCRIPTION</u>	
BS-691613	Exhaust Gasket	Qty 2
703-3099	Exhaust Pipe Shield	Qty 1
910-1268	Hex Screw #10-16 x .375	Qty 2
910-3292	Cap Screw M8-1.25 x 20 mm	Qty 4
912-3004A	Flange Nut 5/16-18	Qty 3
751-0655	Exhaust Pipe (Vanguard Twin)	Qty 1
951-3001	Muffler Assembly	Qty 1

**MODEL 2185
759-3944 MUFFLER SERVICE KIT**

consists of

<u>PART NUMBER</u>	<u>DESCRIPTION</u>	
KH-M-0841080	Flange Nut M8-1.25	Qty 4
KH-24-041-02	Exhaust Gasket	Qty 2
703-3099	Exhaust Pipe Shield	Qty 1
910-1268	Hex Screw #10-16 x .375	Qty 2
912-3004A	Flange Nut 5/16-18	Qty 3
751-0654	Exhaust Pipe (Kohler Twin)	Qty 1
951-3001	Muffler Assembly	Qty 1



* Until depleted, remaining stock will be used.

This is being released for informational purposes only.

Service Manager	Parts Manager	Sales Manager	Service Tech.	Service Tech.

Circulate and Initial