

MTD ENGINES (Vertical)

Part Affected: 711-06413 Camshaft
Engine Model Affected: 4X90HU MTD X90 Series Vertical Shaft Engines
Date: March 27, 2017
Subject: X90 Cam/Tappet Kit 753-08688

INFORMATIONAL ONLY

NOTE: These materials are prepared for use by trained technicians who are experienced in the service and repair of equipment of the kind described in this publication, and are not intended for use by untrained or inexperienced individuals. Such individuals should seek the assistance of an authorized service technician or dealer.

NOTE: Always wear eye protection while servicing equipment. Wear hearing protection when appropriate. Always work in a well ventilated area and follow all safety precautions when dealing with combustible materials.

NOTE: Left (LH) and Right (RH) sides are determined from the operator's position and facing in the forward direction.

PURPOSE:

If a customer is complaining of low power / hard starting on a unit with the above mentioned engine, check the intake lobe of the camshaft to see if the lobe is wearing. If wear is confirmed order a **753-08688** X90 Cam/Tappet Kit.

NOTE: The 753-08688 X90 Cam/Tappet Kit Does Not contain gaskets. All related gaskets will need to be ordered separately.

Service Kit Contents

(See Figure 1)

ITEM NO.	PART NUMBER	QTY	DESCRIPTION
1	619-05216	1	CAMSHAFT - X90
2	751-15614	2	TAPPET - X90
	*	1	THIS INSTRUCTION SHEET

* - Not Available Separately




FIGURE 1

This Advisory is being released for informational purposes only.

SERVICE MANAGER	PARTS MANAGER	SALES MANAGER	SERVICE TECH.	SERVICE TECH.

Circulate and Initial