



# Service Advisory

## HOME MAINTENANCE

CC-492

Models Affected: LT 1042 (13BX11CG709, 13BX11CG710, 13BX11CG712)

Serial Number Range Affected: 1E195H10134 and Prior.

Date: **May 05, 2005**

Subject: **Isolator Kit**

PURPOSE: To isolate the vibration present in the single cylinder, single deck belt design Series 1000 LT 1042 tractor.

ACTION: A service kit has been developed and can be installed on all LT 1042 Series 1000 Lawn Tractors in the affected serial number range. This kit will help isolate the vibrations incurred in a single cylinder, single deck belt designed unit. The photo at the right (Figure 1) shows the contents of the Isolator Kit.

**FIGURE 1**



### Service Kit Contents

| ITEM NO. | PART NUMBER | QTY | DESCRIPTION                         |
|----------|-------------|-----|-------------------------------------|
| 1        | 710-0528    | 2   | 5/16" -18 x 1.25" Bolt              |
| 2        | 731-05291   | 2   | Vinyl Trim Strip 2.50" Lg.          |
| 3        | 735-0690    | 2   | Grommet .4375" ID x .750"           |
| 4        | 750-3310    | 2   | Flange Spacer .312" x .437" x .625" |
| 5        | 777I22568   | 1   | Throttle Instruction Label          |
| 6        | 777S32531   | 1   | Warning/Safety Label                |
| 7        | 769-01806   | 1   | Instruction Sheet                   |

The installation of the Isolator Kit and the attention to the proper engine RPM of 3400 RPM at no load speed, will alleviate any excess vibration incurred in the unit.

**PARTS ORDERING INFORMATION:** Do not attempt to order the parts or service kit, as they will be shipped to you free of charge based on the quantity of tractors identified by serial number/date code on the **DEALER/CUSTOMER INFORMATION FORM**. See attached form.

If you require technical assistance call 1-330-273-4550.

**WARRANTY:** Normal warranty terms apply. Indicate Service Advisory **CC-492** and **710-0451** as the original failed part on the claim. Repair time allowance of **0.5 Hrs.** has been determined to properly install the contents of the kit and to perform the required adjustments to obtain the recommended engine RPM. There is no need to fill out the parts section of the claim because you received the parts free of charge.

| SERVICE MANAGER | PARTS MANAGER | SALES MANAGER | SERVICE TECH. | SERVICE TECH. |
|-----------------|---------------|---------------|---------------|---------------|
|                 |               |               |               |               |

Circulate and Initial

