




Models: Series 2000 Tractors
 Date: August 8, 1997
 Subject: FRONT LIGHT ASSEMBLY

The 731-3138 lens and 731-3150 headlight reflector are being discontinued. Stock of these parts are to be used until depleted. When depleted, use part number 725-3257 headlight reflector and lens assembly with bulbs.

NOTE: As stock is depleted, Shelby Parts Depot will substitute 725-3257 for 731-3138. Part number 731-3150 will be listed as no longer available.



725-3257
FRONT LIGHT ASSEMBLY WITH BULBS
LIST PRICE \$ 67.00*

*Price subject to change without notice.

Warranty Allowance: This is a product improvement, therefore updating of units does not qualify under warranty.

Service Manager	Parts Manager	Service Tech.	Service Tech.	Service Tech.

Circulate and Initial