



Service Advisory

Series 2000/2500

CC-538A

Models Affected: GT 2542 (14A-2D2G710)
GT 2544 (14A-2C7L710)
GT 2550 (14A-2E7P710)
GT 2554 (14A-2A7K710)

Serial Number Range Affected: Above tractor models built January 13, 2006 & after. (1A136G & after).


Date: August 23, 2006 **Revised On November 10, 2008 (Destroy All Previous Copies).**

Subject: **759-04137A Hood Service Kit**


PURPOSE: When a hood is required and the unit is without a heat shield extension, order **759-04137A Hood Service Kit**. This service kit includes a hood plus an additional exhaust heat shield to help redirect heated exhaust air away from the lower portion of the hood and latch assembly area.

IMPORTANT ATTENTION PARTS MANAGER ATTENTION SERVICE MANAGER

NOTE: Decals & labels are NOT INCLUDED in the 759-04137A Hood Service Kit. All decals & labels for the hood must be ordered separately and the part numbers are shown on the reverse side of this advisory.



UNIT WITHOUT HEAT SHIELD EXTENSION



UNIT WITH HEAT SHIELD EXTENSION

Parts List for the 759-04137A listed on reverse side.

Service Kit Contents 759-04137A

ITEM NO.	PART NUMBER	QTY	DESCRIPTION
1	703-05947	1	Muffler Extension Shield
2	726-0233	4	Push Nut
3	728-0177	3	Pop Rivet 3/16 x .450"
4	731-05161	1	Hood Cover
5	731-06887	1	Hood
6	736-0400	3	Flat Washer .194" x .62" x .063"
7	710-1242	4	5/16-14 x .75 HiLow Screw

Instruction Sheet included with kit.

NOTE: The Hood Kit 759-04137A Does Not Include Labels. All Labels Need To Be Ordered Per Tractor Model. Below Is A List Of Labels Available. All Models Require The L.H & R.H. Hood Stripe (Cub Cadet) Labels. Order Model Designation Labels As Required.

List Of Labels

MODEL NO.	PART NUMBER	QTY	DESCRIPTION
ALL	777D09722	1	L.H. Hood Stripe (Cub Cadet)
ALL	777D09721	1	R.H. Hood Stripe (Cub Cadet)
GT 2542	777D09713	A/R	L.H. GT 2542 Label
GT 2542	777D09714	A/R	R.H. GT 2542 Label
GT 2544	777D09716	A/R	L.H. GT 2544 Label
GT 2544	777D09715	A/R	R.H. GT 2544 Label
GT 2550	777D09717	A/R	L.H. GT 2550 Label
GT 2550	777D09718	A/R	R.H. GT 2550 Label
GT 2554	777D09720	A/R	L.H. GT 2554 Label
GT 2554	777D09719	A/R	R.H. GT 2554 Label




FIGURE 1

Warranty: Normal warranty terms apply. Indicate Service Advisory **CC-538A** and **703-05875A** as the original failed part on the claim. Repair time allowance is 1.0 Hrs.

SERVICE MANAGER	PARTS MANAGER	SALES MANAGER	SERVICE TECH.	SERVICE TECH.

Circulate and Initial